Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	10	toroid and inverter and polyphase	USPAT	OR	ON	2005/04/04 07:08
L4	560	brushless same motor same inverter	USPAT	OR	ON	2005/04/04 08:12
L5	109	L4 and ripple	USPAT	OR	ON	2005/04/04 08:12
L6	2	("20020060548"   "6169670").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/04 08:54
L7	216	"109" and coreless	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/04 08:54
L8	216	7 and coreless	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/04 08:55
L9	2	5 and coreless	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/04 08:59
L10	16	(coreless adj5 motor) and transformer	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/04 08:59
L11	31	(US-3792286-\$ or US-3876923-\$ or US-4204264-\$ or US-5040105-\$ or US-5041957-\$ or US-5041958-\$ or US-5191518-\$ or US-5193054-\$ or US-5198971-\$ or US-5212629-\$ or US-5245525-\$ or US-5317498-\$ or US-5337227-\$ or US-5355296-\$ or US-5434771-\$ or US-5446643-\$ or US-5515264-\$ or US-5559686-\$ or US-5657214-\$ or US-5657217-\$ or US-5666278-\$ or US-5764504-\$ or US-5852554-\$ or US-5859769-\$ or US-5933339-\$ or US-6101109-\$). did. or (US-6154378-\$ or US-6201720-\$ or US-6252362-\$ or US-6348775-\$ or US-6356043-\$). did.	USPAT	OR	ON	2005/04/04 10:17
L12	12	L11 and brushless	USPAT	OR	ON	2005/04/04 10:18
L13	1	12 and (not generator)	USPAT	OR	ON	2005/04/04 10:18
S1	20	("3154695" "3638094" "3678367" " 3769569" "3792286" "3879650" "40 70605" "4225914" "4599686" "5041 768" "5132892" "5294875" "565070 8" "5798623" "0015904" "6304045"  "1130519" "6348775" "6459361" " 0053323").PN.	USPAT	OR	OFF	2005/03/30 12:35
S4	3	"6459221"	USPAT	OR	OFF	2005/03/30 11:31
S7	1	"6459221".pn.	USPAT	OR	OFF	2005/03/29 14:47
S18	1	"20010030519".did.	US-PGPUB	OR ·	ON	2005/03/29 15:30

			<del>,</del>		· · ·	
S20	1	"20030053323".did.	US-PGPUB	OR	ON	2005/03/29 15:16
S21	1	"20010015904".did.	US-PGPUB	OR	ON	2005/03/29 15:19
S22	3566	(318/801,802,254,727).CCLS.	USPAT; USOCR	OR	OFF	2005/04/04 10:31
S23	185	S22 and poly\$1phase and inverter	USPAT	OR	ON	2005/03/30 12:37
S24	3557	(318/801,802,254,727).CCLS.	USPAT; USOCR	OR	OFF	2005/03/30 11:27
S25	191	S24 and poly\$1phase and inverter	USPAT	OR	ON	2005/03/30 11:27
S26	0	S25 and sub\$1phase\$1	USPAT	OR	ON	2005/03/30 11:28
S27	47	inverter and sub\$1phase\$1	USPAT	OR	ON	2005/03/30 11:29
S28	3019	(363/65,71,131-135).CCLS.	USPAT; USOCR	OR	OFF	2005/03/30 12:36
S29	134	S28 and poly\$1phase and inverter	USPAT	OR	ON	2005/03/30 13:06
S30	16	(S24 or S28) and "summing transformer"	USPAT	OR	ON	2005/03/30 13:47
S31	3	(S24 or S28) and (harmonic adj block\$2)	USPAT	OR	ON	2005/03/30 15:23
S32	46	(S24 or S28) and interphase same (transformer or reactor)	USPAT	OR	ON	2005/03/30 15:18
S33	8838	interphase toroid	USPAT	OR	ON	2005/03/30 15:19
S34	7	interphase and toroid	USPAT	OR	ON	2005/03/30 15:21
S35	31	S32 and multipl\$5	USPAT	OR	ON	2005/03/30 15:30
S36	516	transformer same multiplies	USPAT	OR	ON	2005/03/30 15:32
S37	111	transformer adj8 multiplies	USPAT	OR	ON	2005/03/30 15:35
S38	1278	"111" and (switching adj frequency)	USPAT	OR	ON	2005/03/30 15:36
S39	5	S37 and (switching adj frequency)	USPAT	OR	ON	2005/03/30 15:40
S40	1377	(transformer adj8 divide\$1) and voltage	USPAT	OR	ON	2005/03/30 15:42
S41	93	S40 and "voltage step"	USPAT	OR	ON	2005/03/30 15:41
S42	93	(transformer adj8 divide\$1) and "voltage step"	USPAT	OR	ON	2005/03/30 15:43
S43	0	(transformer adj8 divide\$1) adj8 "voltage step"	USPAT	OR	ON	2005/03/30 15:43
S44	0	(transformer adj8 divide\$1) adj8 "maximum voltage"	USPAT	OR	ON	2005/03/30 15:44
S45	132	(transformer adj8 divide\$1) adj8 voltage	USPAT	OR	ON	2005/03/30 15:57
S46	35	coreless adj5 brushless adj5 motor	USPAT	OR	ON	2005/03/30 16:09
S47	297	coreless adj5 motor	USPAT	OR	ON	2005/03/30 16:16
S48	14	(S24 or S28) and subinverter	USPAT	OR	ON	2005/03/30 16:20
S49	1	("5353155").PN.	USPAT; USOCR	OR	OFF	2005/03/31 15:40

S50	1	("5253155").PN.	USPAT; USOCR	OR	OFF	2005/03/31 15:40
S51	31	(US-3792286-\$ or US-3876923-\$ or US-4204264-\$ or US-5040105-\$ or US-5041957-\$ or US-5041958-\$ or US-5191518-\$ or US-5193054-\$ or US-5198971-\$ or US-5212629-\$ or US-5245525-\$ or US-5317498-\$ or US-5337227-\$ or US-5355296-\$ or US-5434771-\$ or US-546643-\$ or US-5515264-\$ or US-5559686-\$ or US-5657214-\$ or US-5657217-\$ or US-5666278-\$ or US-5764504-\$ or US-5852554-\$ or US-5859769-\$ or US-5933339-\$ or US-6101109-\$). did. or (US-6154378-\$ or US-6201720-\$ or US-6252362-\$ or US-6348775-\$ or US-6356043-\$). did.	USPAT	OR	ON	2005/04/04 10:16
S52	4	S51 and ("metal oxide" or MOS)	USPAT	OR	ON	2005/04/01 09:17
S53	0	S51 and toroid	USPAT	OR	ON	2005/04/01 09:17
S54	4190	"31" and brushless	USPAT	OR	ON	2005/04/01 10:41
S55	12	S51 and brushless	USPAT	OR	ON	2005/04/04 08:12
S56	1	("4698739").PN.	USPAT; USOCR	OR	OFF	2005/04/01 10:58
S57	679876	brushless sam motor	USPAT	OR	ON	2005/04/01 11:08
S58	7703	brushless same motor	USPAT	OR	ON	2005/04/01 11:08
S59	560	brushless same motor same inverter	USPAT	OR	ON	2005/04/01 11:11
S60	137	S59 and transformer	USPAT	OR	ON	2005/04/01 11:11
S61	307422	"31" and motor	USPAT	OR	ON	2005/04/01 14:54
S62	15	S51 and motor	USPAT	OR	ON	2005/04/01 15:21
S63	12	toroids and tranformers	USPAT	OR	ON	2005/04/01 15:22
S64	4109	toroid\$2 and transformer	USPAT	OR	ON	2005/04/01 15:47
S65	2647	S64 and similar	USPAT	OR	ON	2005/04/01 15:49
S66	411	S65 and inverter	USPAT	OR	NO.	2005/04/01 15:49